



1. Inspect Logs on Mobile

When a law enforcement officer requests to view your logs, open the Trackon HOS App. In the left slide menu on top of your screen, tap “DOT Inspections”



2. Then, tap the “BEGIN NEW INSPECTION” button.



3. DRIVER: Select “Record Violations” to recap DOT officer violations found




4. Next, continue inspection by taping Create Inspection Report.



5. Use the Following Tools:

Record conversation or Take photo.


Choose photo that you’ve taken and tap Finish Inspection.




6. Type in ODOMETER number. Attach a photo to the specified defect are. Proceed further.



7. Assess vehicle condition, Sign up and Save the Report.




HOW TO TRANSFER ERODS



Click icon to view the log/doc you need




Click icon to send ERODS



Email Logs


Enter routing code provided by the authorized safety official



Turn over to learn more about how to read the drivers log

View Logs and Inspection Reports

In Inspection Mode, you will have access to the logs and vehicle inspection reports for the most recent 30 days. For each day, you will find a log chart that visually depicts the duration of the driver's activity over the 24 hour period and any vehicle inspection reports the driver created for that day



DRIVER'S DAILY LOG

(ONE CALENDAR DAY - 24 HOURS)

08 05 2017
MONTH DAY YEAR

500.0
TOTAL MILES DRIVING TODAY

I hereby certify that my data entries and my record of duty status for this 24-hour period are true and correct.

VEHICLE NUMBER _____

TRAILER NUMBER(S) _____

TrackOn Systems LLC.

NAME OF CARRIER OR CARRIERS

7667 West 95th St. Hickory

MAIN OFFICE ADDRESS

DRIVER'S SIGNATURE *Test Driver1*

NAME OF CO-DRIVER _____

Day Log form details required by DOT and FMSCA

Total miles driving today.

Each number below the log chart corresponds to the first number of every row of the table.

The table shows you the details of each duty status period, including Location and Notes.

	M	1	2	3	4	5	6	7	8	9	10	11	N	1	2	3	4	5	6	7	8	9	10	11	M	TOTAL HOURS
OFF DUTY																										9.0
SLEEPER																										11.5
DRIVING																										0.0
ON DUTY																										3.5
OILFIELD WAITING																										0.0
																										24.0


No	EVENT/STATUS	START(UTC-05:00)	DURATION	ODOMETER	ENGINE HOURS	LOCATION	ORIGIN	NOTES
1	OFF DUTY	12:00 AM	9 h 0 m	0.0	0.0	-	Driver	-
2	ON DUTY	09:00 AM	3 h 30 m	0.0	0.0	-	Driver	-
3	SLEEPER	12:30 PM	11 h 30 m	0.0	0.0	-	Driver	-
	-	08-Aug-17 11:19 AM	-	0.0	0.0	Willowbrook, IL 60527, USA	Driver	Log Signed

SHIPPING DOCUMENTS NO. _____

Inspection Report's non-defect related details.

All defects reported by the driver categorized by tractor and trailer.

The Mechanic's signature certifying that the defects were corrected or need not be corrected (If applicable).



DRIVER'S VEHICLE INSPECTION REPORT

August 07, 2017
04:17 PM CDT

DRIVER	Test Driver1	CARRIER	TrackOn Systems LLC.
ODOMETER	5555	LOCATION	3417 S Cicero Ave, Cicero, IL 60804, USA
VEHICLE	1	TRAILERS	001
No Remarks Found			
Front Headlights: broken Front Brakes: squeaking Front Steering: not working Driver Front Axle Wheels: wearing uneven		No Defects Found	

Condition of the above vehicle is satisfactory

Defects have been corrected

Repair not required for safe operation of the vehicle

DRIVER'S SIGNATURE *Test Driver1*

DRIVER'S SIGNATURE _____

MECHANIC SIGNATURE _____